




Machine Extension (mm)


C04





Machine Extension (mm)


C05






Machine Extension (mm)

C06






Machine Extension (mm)





Machine Extension (mm)





Machine Extension (mm)

C09

Greatest Slope Point #1

L


L1

324,40  
324,30  
324,20  
324,10  
324,00  
323,90  
323,80  
323,70  
323,60  
323,50

5

10


Time (Minutes)





Machine Extension (mm)


C10





Machine Extension (mm)

C11








Machine Extension (mm)


C12





Machine Extension (mm)


C13





Machine Extension (mm)


C14






Machine Extension (mm)

C15






Machine Extension (mm)





Machine Extension (mm)


C17






Machine Extension (mm)

C18





Machine Extension (mm)








Machine Extension (mm)


C20





Machine Extension (mm)


C21





Machine Extension (mm)


C22





Machine Extension (mm)


C23





Machine Extension (mm)


C24





Machine Extension (mm)


C25





Machine Extension (mm)


C26





Machine Extension (mm)

C27









Machine Extension (mm)

C28





Machine Extension (mm)





Machine Extension (mm)

C30

Greatest Slope Point #1

L


L1

324,00  
323,90  
323,80  
323,70  
323,60  
323,50  
323,40  
323,30  
323,20  
323,10

5

10


Time (Minutes)





Machine Extension (mm)


C31






Machine Extension (mm)

C32






Machine Extension (mm)






Machine Extension (mm)

C34





Machine Extension (mm)








Machine Extension (mm)


C36





Machine Extension (mm)


C37





Machine Extension (mm)


C38





Machine Extension (mm)


C39





Machine Extension (mm)


C40





Machine Extension (mm)


C41





Machine Extension (mm)


C42





Machine Extension (mm)

C43








Machine Extension (mm)


C44





Machine Extension (mm)


C45





Machine Extension (mm)


C46





Machine Extension (mm)


C47





Machine Extension (mm)


C48





Machine Extension (mm)


C49





Machine Extension (mm)


C50





Machine Extension (mm)

C51








Machine Extension (mm)


C52





Machine Extension (mm)


C53





Machine Extension (mm)


C54





Machine Extension (mm)


C55





Machine Extension (mm)


C56





Machine Extension (mm)


C57





Machine Extension (mm)


C58





Machine Extension (mm)

C59








Machine Extension (mm)

C60

324,70  
324,60  
324,50  
324,40  
324,30  
324,20  
324,10  
324,00  
323,90  
323,80


Time (Minutes)






Machine Extension (mm)

C61






Machine Extension (mm)





Machine Extension (mm)

C02





Machine Extension (mm)

C03

