




Machine Extension (mm)

B01





Machine Extension (mm)

B02

323,90  
323,80  
323,70  
323,60  
323,50  
323,40  
323,30  
323,20  
323,10  
323,00

5


10

Time (Minutes)

Greatest Slope Point #1

L


L1





Machine Extension (mm)


B03





Machine Extension (mm)


B04





Machine Extension (mm)


B05





Machine Extension (mm)

B06





Machine Extension (mm)

B07

Greatest Slope Point #1

L


L1

323,90  
323,80  
323,70  
323,60  
323,50  
323,40  
323,30  
323,20  
323,10  
323,00

5

10


Time (Minutes)





Machine Extension (mm)

B08








Machine Extension (mm)


B09





Machine Extension (mm)


B20





Machine Extension (mm)


B21






Machine Extension (mm)

B10





Machine Extension (mm)






Machine Extension (mm)

B12

322,90  
322,80  
322,70  
322,60  
322,50  
322,40  
322,30  
322,20  
322,10  
322,00




Time (Minutes)



Machine Extension (mm)

B13





Machine Extension (mm)

B22

Greatest Slope Point #1

L


L1

322,90  
322,80  
322,70  
322,60  
322,50  
322,40  
322,30  
322,20  
322,10  
322,00

5

10

Time (Minutes)








Machine Extension (mm)


B23





Machine Extension (mm)


B14





Machine Extension (mm)


B15





Machine Extension (mm)


B16





Machine Extension (mm)


B17





Machine Extension (mm)

B18





Machine Extension (mm)

B19

